

GOVT OF ASSAM  
OFFICE OF THE EXECUTIVE ENGINEER ::: P.W.D. ::: NAGAON ,RAHA,DHING &  
BATADRAVA TERRITORIAL BUILDING DIVISION  
NAGAON :: ASSAM

**// FITNESS CERTIFICATE //**

This is to certify that the R.C.C(G+2) Building of **Nagaon Girls' College at Nagaon, Assam**, pin No.782002, has been checked and it seems to be structurally safe as per visual inspection as reported by the concern Assistant Executive Engineer PWD, Nagaon Territorial Building Sub-Division, Nagaon.

*sdk*  
( Er.Kangkan Barman)  
Executive Engineer, PWD  
Nagaon,Raha,Dhing & Batadrava  
Territorial Building Division ,Nagaon.

Memo No. NBD/TB /Fitness School+Coll/2023 / 1035-A /

Date: 10.05.2024

Copy to :

1. ✓ The Principal, Nagaon Girls' College, Nagaon, Assam, for information with reference to his letter no. NGC/217/RUSA/2024/4158 Dtd. 06-05-2024.  
Enclo: Photocopy of report submitted by Asstt. Executive Engineer, PWD, Nagaon Territorial Building Sub-Division, Nagaon.
2. The Asstt. Executive Engineer, PWD, Nagaon Territorial Building Sub-Division, Nagaon for information.

*10/05/24*  
(Er.Kangkan Barman)  
Executive Engineer, PWD  
Nagaon,Raha,Dhing & Batadrava  
Territorial Building Division ,Nagaon.  
*07-05-2024*

To

The Assistant Executive Engineer, PWD  
Nagaon Territorial Building Sub-Division, Nagaon

Sub: Submission of building safety certificate.

Ref: NGC/217/RUSA/2024/4158 Dtd. 06-05-2024

Madam,

With reference to the subject cited above, I have the honour to inform you that after verification of site the following observation are made of G+2 RCC building of Nagaon Girls College which was constructed in 2017 with (plinth area for ground floor 142.60 m<sup>2</sup>, 1<sup>st</sup> floor=142.60 m<sup>2</sup> and 2<sup>nd</sup> floor = 142.60 m<sup>2</sup>.)

The following observations are found:

1. Plinth level of the building as per norms.
2. All floor (G.F, 1<sup>st</sup> floor & 2<sup>nd</sup> Floor) are in good condition.
3. Toilet facilities and drinking water is available.
4. Fire- fighting is available.
5. Proper lighting and ventilation system is available.

This is for favour of your kind information and take necessary action.


Yours faithfully,

  
9/5/24  
Assistant Engineer, PWD  
Nagaon, Raha, Chhipa & Batadrava  
Territorial Building Division  
Nagaon, Raha, Chhipa & Batadrava  
Territorial Building Division, Nagaon

For

EE, PWD (Bldg)

The above mentioned bldg is checked & the observations mentioned are found correct & the bldg is found to be structurally safe as per visual observation.

  
9/5/24  
Asst. Ex. Engineer, PWD  
Nagaon Territorial  
Building Sub-Divn